

	Typ	L	Hi	Search Text	DBs	Time Stamp	Co	Er	Er
	pe	#	ts				m	ror	ror
							en	De	s
							ts	fin	
								iti	
								on	
1	BR	L1	21	(wavy undulat\$) same passivat\$	USPAT	2001/07/01 15:14			0
2	BR	L2	3	("3247927" "4031272" "5162240").PN.	USPAT	2001/07/01 15:18			0
3	BR	L3	2	5358733.URPN.	USPAT	2001/07/01 15:21			0
	S								
	S								
	S								

	Type	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
1	BR S	26 27 99	bump ball	USPAT	2001/06/28 20:52			0
2	BR S	12 59 53 1	via hole throughhole	USPAT	2001/06/28 20:55			0
3	BR S	40 39 76	epoxy resin	USPAT	2001/06/28 20:55			0
4	BR S	15 00 23 3	cover\$ fill\$ seal\$	USPAT	2001/06/28 20:56		Truncation Overflow. Return string from Server is: 5'0'0'COV	1
5	BR S	76 00	(bump ball) near (cover\$ fill\$ seal\$) (via hole throughhole) near5 (epoxy resin) near5 (cover\$ fill\$ seal\$)	USPAT	2001/06/28 20:56			0
6	BR S	15 3	((bump ball) near (cover\$ fill\$ seal\$) (via hole throughhole) near5 (epoxy resin) near5 (cover\$ fill\$ seal\$)) and (438/613-617.ccls. 257/737,738.ccls. 228/180.22.ccls.)	USPAT	2001/06/28 21:01			0
7	BR S	12 2	((bump ball) near (cover\$ fill\$ seal\$) (via hole throughhole) near5 (epoxy resin) near5 (cover\$ fill\$ seal\$)) and (438/613-617.ccls. 257/737,738.ccls. 228/180.22.ccls.)) and (@ad<19971030 @rlad<19971030 @prad<19971030)	USPAT	2001/06/28 21:07			0
8	BR S	20	(bump ball) near5 (via hole throughhole) near5 (epoxy resin) near5 (cover\$ fill\$ seal\$)	USPAT	2001/06/28 21:07			0

	Ty pe	Hi ts	Search Text	DBs	Time Stamp	Co m m en ts	Er ror De fin iti on	Er ror s
9	BR S	3	((bump ball) near5 (via hole throughhole) near5 (epoxy resin) near5 (cover\$ fill\$ seal\$)) and (438/613-617.ccls. 257/737,738.ccls. 228/180.22.ccls.) and (@ad<19971030 @riad<19971030 @prad<19971030)	USPAT	2001/06/28 21:09			0
10	BR S	10 17	((bump ball) near5 (via hole throughhole) near5 (cover\$ fill\$ seal\$))	USPAT	2001/06/28 21:09			0
11	BR S	9	("3832769" "4249302" "4811081" "5010308" "5225966" "5502889" "5607877" "5677576" "5886415").PN.	USPAT	2001/06/28 21:12			0
12	BR S	0	6121688.URPN.	USPAT	2001/06/28 21:17			0
13	BR S	7	("5014111" "5274916" "5384952" "5407864" "5615477" "5843251" "5848466").PN.	USPAT	2001/06/28 21:21			0
14	BR S	86 68	blind adj (throughhole (through hole))	USPAT	2001/06/29 17:27			0
15	BR S	19 03	438/613-617.ccls. 257/737,738.ccls. 228/180.22.ccls.	USPAT	2001/06/29 17:26			0
16	BR S	15	(blind adj (throughhole (through hole))) and (438/613-617.ccls. 257/737,738.ccls. 228/180.22.ccls.)	USPAT	2001/06/29 17:26			0
17	BR S	66	blind adj (throughhole (through adj hole))	USPAT	2001/06/29 17:52			0
18	IS & R	3	((("6121688") or ("5892273") or ("5366906"))).PN.	USPAT	2001/06/29 19:21			0
19	BR S	9	("3832769" "4249302" "4811081" "5010308" "5225966" "5502889" "5607877" "5677576" "5886415").PN.	USPAT	2001/06/29 18:10			0
20	IS & R	1	("6051093").PN.	USPAT	2001/06/29 19:23			0
21	BR S	7	("5014111" "5274916" "5384952" "5407864" "5615477" "5843251" "5848466").PN.	USPAT	2001/06/29 19:22			0
22	IS & R	1	("6051093").PN.	DERWEN T	2001/06/29 19:27			0
23	BR S	1	US-6051093-A.DID.	DERWEN T	2001/06/29 19:24			0
24	BR S	16	"0145251"	DERWEN T	2001/06/29 19:29			0
25	IS & R	0	("0145241").PN.	DERWEN T	2001/06/29 19:29			0
26	BR S	15	"0145241"	DERWEN T	2001/06/29 19:30			0
27	BR S	1	"01045241"	DERWEN T	2001/06/29 19:31			0
28	IS & R	5	("1045241").PN.	DERWEN T	2001/06/29 19:32			0

	Type	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
29	BR S	44 53	tsukahara.in.	USPAT; EPO; JPO; DERWEN T	2001/06/29 19:32			0
30	BR S	19 51	norihito.in.	USPAT; EPO; JPO; DERWEN T	2001/06/29 19:32			0
31	BR S	14	tsukahara.in. and norihito.in.	USPAT; EPO; JPO; DERWEN T	2001/06/29 19:32			0
32	BR S	52	((bump ball) near5 (via hole throughhole) near5 (cover\$ fill\$ seal\$)) and (@ad<19971030 @riad<19971030 @prad<19971030) and (438/613-617.ccls. 257/737,738.ccls. 228/180.22.ccls.)	USPAT	2001/06/29 19:47		Truncation Overflow. Return string from Server is: 5'15'26'8'1	1
33	BR S	4	("5262226" "5384952" "5434452" "5681647").PN.	USPAT	2001/06/29 19:59			0
34	BR S	7	("4807021" "5189507" "5237130" "5299730" "5347162" "5363277" "5378869").PN.	USPAT	2001/06/29 20:08			0
35	BR S	9	5742100.URPN.	USPAT	2001/06/29 20:16			0
36	BR S	58	"4807021"	USPAT	2001/06/30 17:04			0

	Type	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
37	IS & R	1	("5366906").PN.	USPAT	2001/06/30 17:09			0
38	BR S	318	probimide pyralin	USPAT	2001/06/30 17:10			0
39	BR S	0	"modulus near1 elasticity"	USPAT	2001/06/30 17:10			0
40	BR S	14549	modulus near1 elasticity	USPAT	2001/06/30 17:11			0
41	BR S	0	(probimide pyralin) same (modulus near1 elasticity)	USPAT	2001/06/30 17:11			0
42	BR S	0	(probimide pyralin) near50 (modulus near1 elasticity)	USPAT	2001/06/30 17:12			0
43	BR S	0	(probimide pyralin) near100 (modulus near1 elasticity)	USPAT	2001/06/30 17:12			0
44	BR S	9	(probimide pyralin) and (modulus near1 elasticity)	USPAT	2001/06/30 17:28			0
45	BR S	44459	polyimide	USPAT	2001/06/30 17:28			0
46	BR S	0	polyimide same "modulus near1 elasticity"	USPAT	2001/06/30 17:28			0
47	BR S	159051	photo\$	USPAT	2001/06/30 17:28		Truncation Overflow. Return string from Server is: 5'0'0'PHO	1

	Typ	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
48	BR S	3	(polyimide same (modulus near1 elasticity)) same photo\$	USPAT	2001/06/30 17:28			0
49	BR S	18 8	polyimide same (modulus near1 elasticity)	USPAT	2001/06/30 19:11			0
50	BR S	95	438/665.ccls.	USPAT	2001/06/30 19:12			0
51	BR S	26 40 39 1	@ad<19971030 @rlad<19971030 @prad<19971030	USPAT	2001/06/30 19:15			0
52	BR S	73	438/665.ccls. and (@ad<19971030 @rlad<19971030 @prad<19971030)	USPAT	2001/06/30 19:21			0
53	BR S	31 36 9	wavy undulat\$	USPAT	2001/06/30 19:21			0
54	BR S	23 55 6	passivat\$	USPAT	2001/06/30 19:21			0
55	BR S	0	(wavy undulat\$) near5 passivat\$	USPAT	2001/06/30 19:22			0